



# Oregon Scientific THGR221 Temperature & Humidity Sensor with LCD for WMR Stations

## Product Images



## Short Description

Additional / replacement temperature and humidity sensor for the following weather stations: RAR502X, RAR502X, WMR86NX, WMR86NSX

## Description

---

Additional / replacement temperature and humidity sensor for the following weather stations: WMR86NX, WMR86NSX, RAR502X, RAR502SX, and non-X version WMR models such as the WMR86N.

**Temperature measurement range** -20 ° C to 60 ° C

**Humidity measurement range** 25% - 95%

## THGR221 Key Features

- Water resistant design
- 3 channel sensor
- Humidity and Temperature LCD display
- Includes AAA battery
- Splash-proof design

## Additional Information

---

Brand	Oregon Scientific
Dimensions	50 x 22 x 96 mm
Batteries	2 x AAA batteries included
Power	Battery only
Ideal For	Interested, Gardeners
Installation	Wall and table mount