



# **Kestrel USB Data Transfer Cable for 5000 Series**

#### **Product Images**

Weather Shop





#### **Short Description**

USB Data Transfer Cable allows wired communication between any model in the Kestrel 5 Series and Windows/Mac computers with a USB port.

### **Description**

#### Transfer data logs and update firmware with this USB cable.

USB Data Transfer Cable allows wired communication between any model in the Kestrel 5 Series and Windows/Mac computers with a USB port. Use the cable and Kestrel LiNK software to install firmware updates and upload logged data from your Kestrel.

Wirelessly connect your LiNK enabled Kestrel 5 series meter to a PC/Mac, using the optional LiNK USB Dongle.

#### Additional Information

Brand	Kestrel
Explanation	Communication between the cable and Kestrel is optical, and therefore does not compromise the Kestrel's watertight seal. This unit requires no external power source. It features a three-foot cable and data transfer speeds of up to 230 Kbps.
Ideal For	Professional, Education, Amateur
Software	Kestrel Communicator Software: Keep an electronic log of your data with the Kestrel Interface. With the Interface and software, data can be quickly and easily downloaded for analysis. With the Communicator software, the Kestrel's data can easily be charted and also exported for long-term storage or use in other applications. Chart entire data logs or custom selections easily, and automatically chart the data with the press of a button. The Interface also allows users to clear the Kestrel's memory banks, and synchronise your computer's date and time with your Kestrel Meter's.

## **Additional Options**

Add Optional Belt Carry Pouch	Kestrel Protective Carry Pouch