



---

# ACCUR8 FT007TH Temperature & Humidity Sensor

## Product Images

---



## Short Description

---

Additional/replacement sensor for the ACCUR8 DWS7100 weather station.

Features an LCD screen that displays current temperature and humidity.

## Description

You can add up to seven additional FT007TH sensors to your existing DWS7100 weather station.

- Temperature measurement range: -40 to +60 °C
- Humidity measurement range: 10 to 99%
- Wall mounting or table display
- 8 channels selectable
- Max transmission range: 100 metres (300 feet) in open area
- Transmission interval: 60 seconds
- 433.92 MHz RF transmission frequency.

## Additional Information

Brand	ACCUR8
Dimensions	45 x 110 x 21mm
Batteries	2 x AAA 1.5V Alkaline or lithium batteries (not included)
Power	Battery only

## Additional Options

Batteries	2 x AAA Alkaline 1.5V Batteries
-----------	---------------------------------